

# APPLICATION & REMOVAL OF WARNING FLAG 1059 WITH RED AG TOOL 1024




PULL ON THE RINGS  
UNTIL THE CLAMP STAYS OPEN.  
ATTACH TOOL TO A HOTSTICK

1



PUT THE CLAMP RING OVER THE PEG ON  
LEFT CUP OF TOOL. **2**  
SWING THE SPRING LOADED RIGHT CUP  
TO THE LEFT & PUT CLAMP INTO CUP.  
RELEASE CUP SO CLAMP IS HELD IN  
TOOL. **3**



SHOWS RINGS HOOKED OVER  
PEG **3**

4



POSITION THE CLAMP UP  
UNDERNEATH THE CONDUCTOR  
AND PUSH UP QUICKLY  
CAUSING IT TO SNAP SHUT



TO REMOVE PUT HOOK  
THRU ONE OF THE FINGER  
RINGS ON SNAP CLAMP AND  
PULL DOWN UNTIL IT OPENS  
THEN LIFT UP TO IT SLIDES  
ONTO THE HOOK TOOL OR  
FALLS TO THE GROUND

HOTSTICK